

TEST REPORT



REPORT NO.: CTNT240226005R

Product name: Motorized F14 Fresnel

Model No.: Motorized F14 Fresnel

Applicant: Aputure Imaging Industries Co., Ltd

Test procedure: Entrustment Test

Shenzhen Zhongwei Testing Technology Co., Ltd.



TEST REPORT**Commission Delegated Regulation (EU) 2019/2015 of 11 March 2019****COMMISSION REGULATION (EU) 2019/2020 of 1 October 2019
laying down ecodesign requirements for light sources and separate control
gears pursuant to Directive 2009/125/EC of the European Parliament and of
the Council**

Report Number : CTNT240226005R

Date of issue : October.22,2024

Laboratory Name : Shenzhen Zhongwei Testing Technology Co., Ltd

Testing location/ address : Room 1A106, 1/F., No.109, Lijia Road, Henggang, Henggang
Street, Longgang District, Shenzhen, Guangdong, China

Tested by (Test Engineer) : Steve Zhou

Steve Zhou

Reviewed By (Supervisor) : Airan Lu

Airan Lu

Approved by (Chief Engineer) : Flight Lee



Applicant's name : Aputure Imaging Industries Co., Ltd

Address : Floor 2 to 4 of Building 21, Jiuwo Longjun Industrial Area, Longping
Community Department, Dalang Street, Longuhua District,
Shenzhen, Guangdong ,P.R. China

Manufacturer name : Aputure Imaging Industries Co., Ltd

Address : Floor 2 to 4 of Building 21, Jiuwo Longjun Industrial Area, Longping
Community Department, Dalang Street, Longuhua District,
Shenzhen, Guangdong ,P.R. China

Factory name : Aputure Imaging Industries Co., Ltd

Address : Floor 2 to 4 of Building 21, Jiuwo Longjun Industrial Area, Longping
Community Department, Dalang Street, Longuhua District,
Shenzhen, Guangdong ,P.R. China

Test specification:

Standard : COMMISSION REGULATION (EU) 2019/2020 of 1 October 2019

This report may not be reproduced in part without permission to avoid ambiguous interpretation.
This report can be checked and verified in the following ways.

Tel: 0755-28680489

E-mail: admin@ctnt-cert.com

Web: www.ctnt-cert.com

Date of receipt of test item..... : Feb.26, 2024

Test period..... : May.14,2024

General remarks:

"(See Enclosure #)" refers to additional information appended to the report.

"(See appended table)" refers to a table appended to the report.

Throughout this report a ☐ comma / ☒ point is used as the decimal separator.

Other important notes:

1. If you have any objection to the inspection results in this report, please submit a written report to the company within 15 days from the date of receipt of the report.
2. Entrusting test only responsible for the incoming samples, and the test results are used by the entrusting party to understand the quality of the samples.
3. This test report is invalid without the "test stamp".
4. This report may not be reproduced in part without permission to avoid ambiguous interpretation.
5. Test items with "*" are subcontracted items.
6. The remaining samples under test must be collected within three months of receipt of the inspection report. If the samples are not collected within the time limit, the laboratory will handle them by selves.

Company name: Shenzhen Zhongwei Testing Technology Co., Ltd.

Address: Room 1A106, 1/F., No.109, Lijia Road, Henggang, Henggang Street, Longgang District, Shenzhen, Guangdong, China

Tel: 086-755-28680489

Email: admin@ctnt-cert.com

Website: www.ctnt-cert.com

General product information:

This product is Motorized F14 Fresnel

Test item description..... : Motorized F14 Fresnel

Trade Mark..... : Aputure

Manufacturer : Aputure Imaging Industries Co., Ltd

Model/Type reference : Motorized F14 Fresnel

Ratings : 48V 0.4A

This report may not be reproduced in part without permission to avoid ambiguous interpretation.
This report can be checked and verified in the following ways.

Tel: 0755-28680489

E-mail: admin@ctnt-cert.com

Web: www.ctnt-cert.com