

# TEST REPORT



REPORT NO.: CTNT2410090150101R

Product name: parking heater

Model No.: XMZ-L-D4

Applicant: Renqiu Xinmaizhong auto parts Co., LTD

Test procedure: Entrustment Test

Shenzhen Zhongweit Gibhrong echnology Co., Ltd.



#### **TEST REPORT**

COMMISSION REGULATION (EU) 2015/1188 of 28 April 2015 implementing Directive 2009/125/EC of the European Parliament and of the Council with regardto ecodesign requirements for local space heaters

## COMMISSION DELEGATED REGULATION (EU) 2015/1186 of 24 April 2015

supplementing Directive 2010/30/EU of the European Parliament and of the Council with regard to the energy labelling of local space heaters

Report Number.....: CTNT2410090150101R

Date of issue.....: Oct.23,2024

Laboratory Name......: Shenzhen Zhongwei Testing Technology Co., Ltd

Longgang District, Shenzhen, Guangdong, China

Tested by(Test Engineer) ...... Schale zeng

Schale Zeng

Reviewed By(Supervisor).....: Oliver Long

Approved by(Chief Engineer)......: Flight Lee

No. 3 Jingnan Innovation Industrial Park, North Linxing Road, North

Economic Development Zone, Rengiu City, Hebei Province

Manufacturer name......: Renqiu Xinmaizhong auto parts Co., LTD

Applicant's name...... Rengiu Xinmaizhong auto parts Co., LT

No. 3 Jingnan Innovation Industrial Park, North Linxing Road, North

Economic Development Zone, Rengiu City, Hebei Province

Factory name....... Renqiu Xinmaizhong auto parts Co., LTD

No. 3 Jingnan Innovation Industrial Park, North Linxing Road, North

Economic Development Zone, Renqiu City, Hebei Province

Test specification:

Standard : COMMISSION REGULATION (EU) 2015/1188 of 28 April 2015

implementing Directive 2009/125/EC and (EU) 2015/1186

of 24 April 2015 of the European Parliament and of the Council with

regard to ecodesign requirements for local space heaters

Test period.....: Oct.17-22,2024

Tel: 0755-28680489

E-mail: admin@ctnt-cert.com

Web: www.ctnt-cert.com



7/4/////	977775772		////////////
CON	OFO	rema	velo.
vater.	iei ai		11 N S .

"(See Enclosure #)" refers to additional information appended to the report.

"(See appended table)" refers to a table appended to the report.

Throughout this report a  $\square$  comma  $I \boxtimes$  point is used as the decimal separator.

#### Other important notes:

- 1. If you have any objection to the inspection results in this report, please submit a written report to the company within 15 days from the date of receipt of the report.
- 2. Entrusting test only responsible for the incoming samples, and the test results are used by the entrusting party to understand the quality of the samples.
- 3. This test report is invalid without the "test stamp".
- 4. This report may not be reproduced in part without permission to avoid ambiguous interpretation.
- 5. Test items with "\*" are subcontracted items.
- The remaining samples under test must be collected within three months of receipt of the inspection report. If the samples are not collected within the time limit, the laboratory will handle them by selves.

Company name: Shenzhen Zhongwei Testing Technology Co., Ltd.

Address: Room 1A106, 1/F., No.109, Lijia Road, Henggang, Henggang Street, Longgang District, Shenzhen,

Guangdong, China

Tel: 086-755-28680489

Email: admin@ctnt-cert.com Website: www.ctnt-cert.com

### General product information:

- This product is parking heater.
- The under test model XMZ-L-D4 and the series models XMZ-L-D3 are identical except model name and appearance decoration. The differences do not affect product safety and performance.
- All tests are carried out on XMZ-L-D4.

Test item description.....: parking heater

Trade Mark.....: Maizhong Technology

Manufacturer.....: Renqiu Xinmaizhong auto parts Co., LTD

Model/Type reference.....: XMZ-L-D4, XMZ-L-D3

Ratings.....: 12/24V=

#### Possible test case verdicts:

- test case does not apply to the test object.....: N/A

- test object does meet the requirement.....: P (Pass)

- test object does not meet the requirement.....: F (Fail)

Tel: 0755-28680489 E-mail: admin@ctnt-cert.com

Web: www.ctnt-cert.com